

repairs are made, and returned to us at the letterhead address within 60 days after the date of this letter.

If you have any questions, please contact me at 561-790-1742 or smassey@sidistrict.com.

Sincerely,

Scott Massey, President

Enclosures: Backflow Preventer Assembly Testing and Repair Report Form